



To: Electrical Contractors

Date: November 29, 2007

Subject: Circuit Breakers

Due to the ongoing deterioration of old Zinco and Sylvania circuit breaker panels, please advise your on-site electricians during renovations to examine buss bars. If any signs of arcing are apparent, advise the owner to install a new panel.

Thank you,

Robert Mahar Building Official